

8

Date: Wednesday, 1/23/2008 11:40:11 AM
User: Kim Johnston

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services Drawing Name : SHORT STEP ASSEMBLY HIGH SKID LH
Job Number : 36932
Estimate Number : 10575
P.O. Number :
This Issue : 1/23/2008 S.O. No. :
Prsht Rev. : NC Part Number : D350591213
First Issue : 1/1 Type : LARGE FAB ASSY Drawing Number : D3078 REV A
Previous Run : 35672 Drawing Revision : A
Material :
Due Date : 2/20/2008 Qty: 5 Um: Each
Written By :
Checked & Approved By : KS 08 01 23
Comment : Est Rev:B 05.10.14 Modified step 10 KJ/EC
Est Rev:C 06-06-19 Added D2732-030 AS PER DSI9294
JLM
Est Rev:C 06-06-27 Revised as per DSI9340 JLM

Additional Product

Job Number:



Seq. #: Machine Or Operation: Description :

1.0 DC DOCUMENT CONTROL



(5)

Comment: DOCUMENT CONTROL

Photocopy bluefile and type labels as per PPP D350-591-213 CHG002

KS 08-01-31

2.0 D2622120C Extrusion



Comment: Qty.: 0.5000 Each(s)/Unit Total : 2.5000 Each(s)

Pick:

Qty Part Number Description Batch
1 D2622-120C Extrusion B35618

SAD 08:01:06

(5)

3.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Cut D2622-120 extrusion to 59.75" long as per Dwg D3078

2-Drill extrusion as per Dwg D3078 using Jig DT8680 for rivets.

3-Deburr

SAD 08:01:06

5

4.0 QC5 INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

KS 08/01/07

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 1/23/2008 11:40:11 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SHORT STEP ASSEMBLY HIGH SKID LH

Job Number: 36932

Part Number: D350591213

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

D30671

End Plate



Comment: Qty.: 1.0000 Each(s)/Unit Total : 5.0000 Each(s)

Pick:

Qty Part Number

Description Batch

1 D3067-1

End Plate 835804

8/08.02.19 5

6.0

D30631

Support



Comment: Qty.: 1.0000 Each(s)/Unit Total : 5.0000 Each(s)

Pick:

Qty Part Number

Description Batch

1 D3063-1

Support 835691

8/08.02.19 5

7.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel end for welding FWD ONLY

2-Weld Support using Jig DT8681, weld Fwd End Plate as per QSI 004 & Dwg D3072

A/R Aluminum Rod M105058
M105244

3-Grind End Plate flush

8/08.02.19 5
8/08.02.19 5
8/08.02.19 5

8.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

8/08.02.19 5

9.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

8/08.02.20 5

10.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

M-L 08/02/20

(5X)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 1/23/2008 11:40:11 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SHORT STEP ASSEMBLY HIGH SKID LH

Job Number: 36932

Part Number: D350591213

Job Number:



Seq. #:

Machine Or Operation:

Description :

11.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

14 08.02.20 5

12.0

D3065041

Step Leg Assembly



Comment: Qty.: 1.0000 Each(s)/Unit Total : 5.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

1 D3065-041

Step Leg Assy

335622

14 08.02.20 5

13.0

D30661

Spacer



Comment: Qty.: 2.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

2 D3066-1

Spacer

336410

14 08.02.20 5

14.0

MS20600AD4W4

Rivets



Comment: Qty.: 16.0000 Each(s)/Unit Total : 80.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

16 MS20600AD4W4

Rivet

1106654

14 08.02.20 5

15.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

Rivet Leg Assembly as per Dwg D3078.

14 08.02.20 5

16.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

14 08.02.20 5

17.0

D30671

End Plate



Comment: Qty.: 1.0000 Each(s)/Unit Total : 5.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

1 D3067-1

End Plate

335804

14 08.02.20 5

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 1/23/2008 11:40:11 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SH0RT STEP ASSEMBLY HIGH SKID LH

Job Number: 36932

Part Number: D350591213

Job Number:



Seq. #:

Machine Or Operation:

Description :

18.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Bevel Aft end for welding

2-Inspect for foreign object as per QSI 024

3-Weld Aft End Plate as per QSI 004 & Dwg D3078

A/R Aluminum Rod ~~M105058~~
M105058

4-Grind End Plate flush

SAD

08-02-20 5
08-02-20 5
08-02-20 5
08/02/21 (5)

19.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

PD 08-02-21 (5)

20.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

08-02-21 (5)

21.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Touch Up Chemical conversion

M-1 08/02/21 (5X)

22.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

08-02-21 (5X)

23.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Wing Walk as per Dwg D3078 and QSI 005 4.4

M-1 08/02/21 (5X)

24.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: Inspect Powder Coat and Wing Walk

8/2/22 54 (5X)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 1/23/2008 11:40:12 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SHORT STEP ASSEMBLY HIGH SKID LH

Job Number: 36932

Part Number: D350591213

Job Number:



Seq. #:

Machine Or Operation:

Description :

25.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

26.0

D22301

Mounting Lug



Comment: Qty.: 2.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2230-1

Clamp

1536747

SP

27.0

D22303

Mounting Lug



Comment: Qty.: 2.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 D2230-3

Clamp

1536748

SP

28.0

D2732

Rubber Extrusion



Comment: Qty.: 1.0500 f(s)/Unit Total : 5.2500 f(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 D2732-030(3" LONG)

Rubber Cushion

1534717

SP

29.0

D2856400

Abrasion Strip



Comment: Qty.: 0.6000 f(s)/Unit Total : 3.0000 f(s)

Pick: Packing Kit

Qty Part Number Description Batch

1 D2856-400(7.2")

Abrasion Strip

1536161

SP

30.0

AN335A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 AN3-35A

Bolt

1105408

8/2/22

SP

5x

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 1/23/2008 11:40:12 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SHORT STEP ASSEMBLY HIGH SKID LH

Job Number: 36932

Part Number: D350591213

Job Number:



Seq. #:

Machine Or Operation:

Description :

31.0

AN411A

Bolt



Comment: Qty.: 6.0000 Each(s)/Unit Total : 30.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

6 AN4-11A

Bolt

M104214

SP

32.0

AN413A

Bolt



Comment: Qty.: 4.0000 Each(s)/Unit Total : 20.0000 Each(s)

Bolt

Batch: M106815

SP

33.0

AN960JD10

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 20.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

4 AN960JD10

Washer

M10667

SP

34.0

AN960JD416

Washer



Comment: Qty.: 12.0000 Each(s)/Unit Total : 60.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

12 AN960JD416

Washer

M106277

SP

35.0

MS21042L3

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 10.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

2 MS21042L3

Nut (or -3)

M106242

SP

36.0

MS21042L4

Nut



Comment: Qty.: 6.0000 Each(s)/Unit Total : 30.0000 Each(s)

Pick: Packing Kit

Qty Part Number Description Batch

6 MS21042L4

Nut (or -4)

M105938

8/2/21

SP

(5x)

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes ☒ No ☐ DQA: ☒ Date: 28/02/22

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 1/23/2008 11:40:12 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SHORT STEP ASSEMBLY HIGH SKID LH

Job Number: 36932

Part Number: D350591213

Job Number:



Seq. #:

Machine Or Operation:

Description :

37.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



0802-22 (5)

Comment: INSPECT 100% KITS FOR COMPLETENESS

38.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D350-591-213

Location: _____

PPP Rev: _____

C

8/2/22

54

(5x)

39.0

QC21

FINAL INSPECTION/W/O RELEASE



(5)

Comment: FINAL INSPECTION/W/O RELEASE

080102/22

Job Completion



11 08.02.22

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



RELEASED
02.09.20

DESIGN CP	DRAWN BY CP	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED #	APPROVED #	DRAWING NO. D3078	REV. A SHEET 1 OF 2
DATE 02.09.11		TITLE STEP ASSEMBLY, HI SHORT SCALE NTS	
A	02.09.11	NEW ISSUE	

Part No.	Description	QTY -041	QTY -042
D3078-041	Step Assembly, High Short (LH)	X	
D3078-042	Step Assembly, High Short (RH)		X
D2622-60	STEP EXTRUSION	1	1
D3063-1	SUPPORT	1	1
D3065-041	LEG ASSEMBLY	1	1
D3066-1	SPACER	2	2
D3067-1	END PLATE	2	2
MS20600AD4W4	RIVET	16	16

GENERAL NOTES:

- 1) -041 SHOWN, FOR -042 INSTALL D3063-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 36932



COPYRIGHT © 2002 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.



DESIGN	<i>SP</i>	DRAWN BY	<i>SP</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHECKED	<i>SP</i>	APPROVED	<i>SP</i>	DRAWING NO. D3078
DATE	02.09.11	TITLE	STEP ASSEMBLY, HI SHORT	REV. A SHEET 2 OF 2
		SCALE	1:20	

RELEASED
02.09.2011



NO. 36832

WORK ORDER

WITHOUT NOTICE

UNCONTROLLED COPY

ENGINEERING

RETURN TO

SHOP COPY